

# Stress Corrosion Cracking Control Measures

B. F. Brown

AN OFFICIAL  
**NACE**  
PUBLICATION



## Contents

	Page
Foreword .....	v
Preface .....	vi
Abstract .....	viii
Chapter 1. Placing the Problem in Perspective .....	1
I. Sustained load environmental cracking .....	1
II. Interaction between failure modes .....	2
III. Theory .....	2
IV. References .....	4
Chapter 2. Test methods and Interpretation of Test Data .....	5
I. Smooth specimen tests under static loads .....	5
II. Precracked (fracture mechanics) specimens under static loads .....	7
III. Constant strain rate tests .....	10
IV. Metallurgical considerations in tests .....	10
V. Interpretation of SCC test data .....	10
VI. References .....	12
Chapter 3. Copper Alloys .....	13
I. Alloy nomenclature .....	13
II. Ammoniacal SCC .....	13
A. Necessary conditions .....	13
B. Case Histories and other illustrations of principles .....	17
III. SCC in other environments .....	19
IV. Miscellaneous measures .....	20
V. Diagnosing SCC .....	20
VI. Theory .....	21
VII. Summary .....	22
VIII. References .....	22
Chapter 4. Aluminum Alloys .....	23
I. Necessary conditions for SCC .....	23
II. Kinetic factors .....	32
III. Inhibitors .....	32
IV. An example of applying the principles to avoid the problem .....	32
V. Nonaqueous environments .....	33
VI. Identifying SCC .....	33
VII. Theory .....	34
VIII. Summary .....	34
IX. References .....	34
Chapter 5. Titanium Alloys .....	35
I. Liquid environments (excluding metals) .....	35
II. Solid and liquid metals .....	38
III. Sustained load cracking in inert environments .....	38
IV. Diagnostic criteria .....	39
V. Theory .....	40
VI. Summary .....	40
VII. References .....	40
Chapter 6. High strength steels .....	43
I. Degree of susceptibility .....	44
II. Control measures .....	47
III. Examples of practices and failures illustrating principles .....	49
IV. Single-load-path designs .....	52
V. Diagnosing SCC .....	53

- VI. Theory ..... 53
- VII. Summary ..... 53
- VIII. References ..... 53
- Chapter 7. Stainless Steels (Austenitic and Ferritic) ..... 55
  - I. Marine environments ..... 55
  - II. Other low temperature environments ..... 57
  - III. Chloride cracking ..... 57
  - IV. Caustic cracking ..... 60
  - V. Oxygen cracking ..... 60
  - VI. Protective measures illustrating principles ..... 61
  - VII. Identifying SCC ..... 62
  - VIII. Theory ..... 62
  - IX. Summary ..... 63
  - X. References ..... 63
- Chapter 8. Nickel Alloys ..... 65
  - I. Chemical industry ..... 65
  - II. Power Industry ..... 65
  - III. Aerospace industry ..... 66
  - IV. References ..... 66
- Appendix—Glossary of Terms ..... 67
- Index ..... 69