



MATERIALS SCIENCE

G K NARULA
K S NARULA
V K GUPTA

CONTENTS

<i>Foreword</i>	iii
<i>Preface</i>	v
1. Introduction	1
1.1 What is materials science / 1.2 Classification of materials / 1.3 Engineering requirements of materials / 1.4 Important properties of engineering materials / 1.5 Material structure	2 4
2. Atomic Structure and Electronic Configuration	5
2.1 Introduction / 2.2 Atomic structure / 2.3 The electron / 2.4 Properties of cathode rays / 2.5 Electron as universal constituent of all matter / 2.6 Protons-positive rays / 2.7 Nucleus / 2.8 Atomic number / 2.9 Atomic weight / 2.10 Isotopes / 2.11 Isobars / 2.12 Avagadro's number / 2.13 Atomic models / 2.14 Vector model / 2.15 Quantum numbers / 2.16 Pauli's exclusion principle / 2.17 Wave mechanics / 2.18 The periodic table	5 23 6 6 8 8 9 9 21 25
3. Crystal Geometry and Structure	28
3.1 Introduction / 3.2 Crystal structure / 3.3 Space lattice / 3.4 Unit cell / 3.5 Crystal systems / 3.6 Atomic packing / 3.7 Co-ordination number / 3.8 Crystal structures for metallic elements / 3.9 Body-centred cubic structure (BCC) / 3.10 Face-centred cubic structure / 3.11 Close-packed hexagonal structures / 3.12 Crystal symmetry / 3.13 Atomic radius / 3.14 Atomic packing factor (APF) / 3.15 Lattice planes and directions (Miller Indices) / 3.16 Important features of miller indices / 3.17 Interplanar spacings	28 28 29 30 31 31 34 34 34 34 35 35 36 38 40 43

4. Bonds in Solids	48
4.1 Introduction	48
4.3 Mechanism of bond formation	49
4.5 Covalent bond	54
4.7 Comparison of bonds	59
4.9 Mixed bonds	60
4.2 Types of bonds	48
4.4 Ionic bond	51
4.6 Metallic bond	56
4.8 Secondary bonds	60
4.10 Chemical bonding and properties of solid materials	61
4.11 Chemical bonding and the periodic table	62
5. Crystal Imperfection	64
5.1 Introduction	64
5.3 Frank-Read source	71
5.2 Types of imperfections	64
5.4 Some salient points in relation to the theory of dislocation	72
6. X-rays	76
6.1 Introduction	76
6.3 Production of X-rays	76
6.5 Scattered X-rays	79
6.7 Beta-rays (β -rays)	80
6.9 Wave nature of X-rays or X-ray diffraction	81
6.10 Bragg's Law	82
6.11 Intensity measurement of X-rays	84
6.12 Bragg's conditions for X-ray diffraction	84
6.13 Bragg' X-ray spectrometer	85
6.14 Mosley's Law	87
6.15 Importance of Mosley's Law	88
6.16 Bragg's law and crystal structure	88
6.17 Practical X-ray diffraction	89
6.18 Laue method	90
6.19 Rotating-crystal method	91
6.20 Powder crystal method	92
6.21 Application of X-rays	93
6.22 X-ray absorption	94
7. Diffusion in Solids	97
7.1 Introduction	97
7.3 Classification of diffusion	97
7.5 Vacancy mechanism	98
7.7 Direct interchange mechanisms	99
7.8 Diffusion coefficient: Fick's Law	100
7.9 Fick's Second Law—Time dependence	102
7.10 Factors affecting the diffusion coefficient	102
7.11 Self-diffusion	103
7.12 Inter-diffusion	103
7.13 Diffusion couple	103
7.14 Diffusion with constant concentration (case-hardening)	104
7.15 Diffusion in oxides and ionic crystals	104
7.16 Grain-boundary and surface diffusion	105
7.17 Activation energy for diffusion	106

8. Deformation of Materials 108

- | | | | |
|---|-----|--|-----|
| 8.1 Introduction | 108 | 8.2 Elastic deformation | 109 |
| 8.3 Plastic deformation | 110 | 8.4 Deformation in poly-crystalline metals | 111 |
| 8.5 Work hardening | 121 | 8.6 Season cracking | 122 |
| 8.7 Bauschinger effect | 122 | 8.8 Yield point phenomenon and related effects | 123 |
| 8.9 Cold-working | 126 | 8.10 Preferred orientation | 126 |
| 8.11 Recovery, recrystallisation and grain growth | 127 | | |
| 8.12 Hot-working | 131 | | |

9. Theory of Alloys: Constitution and Equilibrium Diagrams 134

- | | | | |
|---|-----|---|-----|
| 9.1 Introduction | 134 | 9.2 Basic terms | 134 |
| 9.3 Solid solutions | 135 | 9.4 Hume-Rothery's rules | 137 |
| 9.5 Intermediate compounds or intermediate phases | 138 | | |
| 9.6 Phase diagrams | 139 | 9.7 The phase rule/Gibb's phase rule | 140 |
| | | 9.8 Time-temperature cooling curves | 141 |
| 9.9 Construction of a phase diagram | 142 | 9.10 The lever rule | 142 |
| | | 9.11 Equilibrium diagram of a binary system in which the two metals are completely soluble in the liquid and solid states | 144 |
| 9.13 Eutectoid system | 150 | 9.12 Eutectic systems | 146 |
| 9.14 Peritectic and peritectoid system | 151 | 9.15 Ternary equilibrium diagram | 152 |

10. Phase Transformations 154

- | | | | |
|---|-----|---------------------------------------|-----|
| 10.1 Introduction | 154 | 10.2 Rate of transformation | 154 |
| 10.3 Mechanism of phase transformation or nucleation | 155 | | |
| 10.4 Homogeneous nucleation | 157 | 10.5 Heterogeneous nucleation | 157 |
| | | 10.6 Nucleation and growth | 157 |
| 10.7 Applications of phase transformations | 158 | | |
| 10.8 Micro-constituents of iron-carbon system | 162 | | |
| 10.9 The allotropy of iron | 163 | 10.10 Iron-carbon equilibrium diagram | 164 |
| | | 10.11 Formation of austenite | 170 |
| 10.12 Isothermal transformation—TTT diagram | 172 | | |
| 10.13 Transformation of austenite upon continuous cooling | 174 | 10.14 Martensitic transformation | 175 |

11. Heat Treatment 176

- | | | | |
|------------------------|-----|----------------------------------|-----|
| 11.1 Introduction | 176 | 11.2 Heat-treatment processes | 177 |
| 11.3 Annealing | 177 | 11.4 Normalising | 181 |
| | | 11.5 Hardening | 182 |
| 11.6 Tempering | 190 | 11.7 Sub-zero treatment of steel | 192 |
| | | 11.8 Case hardening | 192 |
| 11.9 Surface hardening | 197 | 11.10 Heat-treatment furnaces | 200 |

x *Contents*

11.11 Temperature measurement or pyrometry	204
11.12 Defects in the heat treatment of steel	205
12. Organic Materials	209
12.1 Introduction	209
12.2 Polymers	209
12.3 Mechanisms of polymerization	210
12.4 Additions in polymers	212
12.5 Polymer structures	213
12.6 Plastics	214
12.7 Elastomers and rubbers	217
12.8 Fibres and filaments	219
12.9 Composite materials	220
12.10 Single crystals	222
12.11 Agglomerated structures	222
12.12 Protective coatings	223
13. Electrical and Magnetic Properties of Materials	227
13.1 Introduction	227
13.2 Resistivity	227
13.3 Conductivity	229
13.4 Semiconductors	233
13.5 Classification of semiconductors on the basis of fermi level and fermi energy	236
13.6 <i>pn</i> Junction as rectifier	237
13.7 Transistors	239
13.8 Insulators	240
13.9 Dielectrics	240
13.10 Ferroelectricity	244
13.11 Electrostriction	246
13.12 Piezoelectricity	247
13.13 Uses of dielectrics	248
13.14 Magnetic properties	248
13.15 Classification of magnetic materials	250
13.16 Magnetostriction	256
13.17 Soft magnetic materials	258
13.18 Hard magnetic materials	259
14. Corrosion	262
14.1 Introduction	262
14.2 Factors influencing corrosion	262
14.3 Types of corrosion	263
14.4 Specific types of corrosion	270
14.5 Control and prevention of corrosion	274
15. Mechanical Properties	281
15.1 Introduction	281
15.2 Definition of common terms used in mechanical properties	281
15.3 Fundamental mechanical properties	287
15.4 Creep	292
15.5 Mechanical tests	296
15.6 Models of fracture	316
15.7 Factors affecting mechanical properties	324
15.8 Technological properties of metals	326
16. Photoelectric Effect	330
16.1 Introduction	330
16.2 Experimental study of the photoelectric effect	330
16.3 Characteristics of the photo-	

electric effect 332	16.4 Laws of photoelectric emission 333
16.5 Einstein's photoelectric emission 334	16.6 Millikan's verification of Einstein's equation 335
16.7 Photoelectric cells 337	16.8 Applications of photoelectric cells 343

INTRODUCTION

17. Powder Metallurgy	347
17.1 Introduction 347	17.2 Applications of powder metallurgy 347
17.3 Advantages of powder metallurgy 348	17.4 Disadvantages and limitations 349
17.5 Design considerations for powder metallurgy 349	17.6 Process description 350
17.7 Secondary operations 357	17.8 Powder metallurgy and fabrication 359
18. Electron Theory of Metals	366
18.1 Introduction 366	18.2 Metallic bonding 366
18.3 Drude and Lorentz theory 367	18.4 Sommersfield free/electron theory 367
18.5 Electron energies in a metal 369	18.6 Zone theory of solids 371
18.7 Factors affecting electrical resistance of materials 376	
<i>Appendices</i>	377
<i>Index</i>	386

