
SUPERALLOYS A Technical Guide

Edited by Elihu F. Bradley



-671-12-1

2-671-12-1



Superalloys

A Technical Guide

Elihu F. Bradley

Consulting Editor



ASM INTERNATIONAL™ Metals Park, OH 44073

Contents

| Chapter 1 |
|---|
| Introduction |
| General.1What is a Superalloy?.2Castings and Forgings.4Wrought Products.4Powder Metallurgy.5New Approaches.5Applications.5Product Forms.6 |
| Chapter 2 |
| Metallurgy of Superalloys 9 |
| Introduction9Iron-Base Superalloys14Nickel-Base Superalloys14Castings and Forgings15Principles of High-Temperature Behavior17Creep/Stress-Rupture17Metallurgical Instabilities18Strengthening Mechanisms20Superalloy Classifications23Iron-Base Superalloys24Cobalt-Base Superalloys25Nickel-Base Superalloys26Conclusion28 |
| Chapter 3 |
| Microstructure |
| Phases and Structures of Superalloys |

| Effects of Prior Microstructure on Properties | |
|---|------------|
| Chapter 4 | |
| Property Overview | 5 3 |
| Materials Selection53Tensile Properties55Creep/Stress-Rupture55Fatigue Strength61Corrosion/Oxidation Resistance65Hot Disk Applications69Burner Applications72Hot Airfoil Applications73 | |
| Chapter 5 | |
| Cryogenic Applications | 5 |
| Introduction.75Materials Selection.75Mechanical Properties.77Tensile Properties.77Fracture Toughness.81Fatigue-Crack Growth.82 | |
| Chapter 6 | |
| Microstructural Degradation, | |
| Overheating, Stability | 9 |
| Introduction | |

| Chapter 7 | |
|---|---|
| Metallography | 9 |
| Introduction 99 Specimen Preparation 99 Macroexamination 99 Microexamination 101 Sectioning 101 Mounting 101 Grinding 101 Rough Polishing 102 Final Polishing 102 Etching 103 Microexamination Techniques 103 Microexamination Techniques 104 Transmission Electron Microscopy 104 Bulk Extraction 106 Solidification Structures in Welded Joints 107 | * |
| Chapter 8 | |
| Castings | 9 |
| Introduction | |
| Forging | Ł |
| Introduction | , |

| Relationship of Fabrication to Heat Treating Cold Working. Effect of Grain Size Effect on Aging. Rates of Work Hardening Welding. Heat Treating of Iron-Base Alloys Stress Relieving and Annealing. Castings. Solution Treating and Aging. Practical Heat Treatment Heat Treating of Nickel-Base Alloys Stress Relieving and Annealing. 177 Practical Heat Treatment Heat Treating of Nickel-Base Alloys Stress Relieving and Annealing. 179 Stress Relieving and Annealing. 179 Atmospheres. Solution Treating. Solution Treating of Cobalt-Base Alloys 180 |
|--|
| Chapter 12 |
| Cleaning, Finishing |
| Machining185Machining Properties185Cutting Tools186Tool Life186Grinding187Cleaning187Removal of Metallic Contaminants188Mechanical Removal188Chemical Removal189Removal of Tarnish189Removal of Reduced Oxide and Scale190Scale190Scale190Scale Conditioning192Acid Pickling192Abrasive Blasting193Wet Tumbling193Wire Brushing193Salt Bath Descaling195Finishing Processes195 |
| Chapter 13 |
| Welding |
| Introduction |

| Brazing of Nickel Superalloys |
|---|
| Chapter 15 |
| Protective Coatings |
| Introduction 233 Environmental Effects 235 Oxidation 235 Hot Corrosion 236 Coatings for Superalloys 236 Coating Requirements 236 Types of Coatings 237 Diffusion Coatings 237 Overlay Coatings 237 Service Characteristics 238 Methods of Applying Diffusion Coatings 239 Methods of Applying Overlay Coatings 239 |
| Chapter 16 |
| Identification, Recycling 241 |
| Introduction .241 Means of Identification. .241 Color .242 Weight .242 Magnetic Testing. .243 Spark Testing .243 Chemical Spot Testing. .245 Testing for Iron .247 Testing for Chromium .247 Testing for Molybdenum .247 Testing for Manganese. .247 Testing for Nickel .247 Testing for Cobalt .248 Summary .248 |

Chapter 17

| ail | ure Analysis and Prevention | n . | | | | | • | | 249 |
|--------|-----------------------------------|-----|------|--|------|--|------|------|------|
| I | ntroduction | | | | | | | | .249 |
| | orrosion | | | | | | | | |
| | Hot Corrosion | | | | | | | | .249 |
| F | ailure in Arc-Welded Superalloys. | | | | | | | | .250 |
| | Fatigue Fracture | | | | | | | | .250 |
| | Conclusions | | | | | | | | .251 |
| | Recommendations | | | | | | | | .252 |
| H | ydrogen Embrittlement | | | | | | . , | | .252 |
| | High-Strength Steel | | | | | | | | .252 |
| 942.02 | Superalloys | | | | | | | | .252 |
| H | igh-Temperature Failure | ٠. | | | | | | | .253 |