


FAILURE OF MATERIALS IN MECHANICAL DESIGN

Analysis, Prediction, Prevention



Second Edition

JACK A. COLLINS

Contents

Chapter 1	The Role of Failure Prevention Analysis in Mechanical Design	1
1.1	Introduction,	1
1.2	A Definition of Design,	2
1.3	A Challenge,	2
1.4	Some Design Objectives,	3
1.5	Closure,	4
	Questions,	4
Chapter 2	Modes of Mechanical Failure	6
2.1	Definition of Failure Mode,	6
2.2	Failure Modes Observed in Practice,	7
2.3	A Glossary of Mechanical Failure Modes,	9
	Questions,	14
Chapter 3	Strength and Deformation of Engineering Metals	16
3.1	Introduction,	16
3.2	Deformation Response to Applied Shear,	21
3.3	Elastic Deformation,	24
3.4	Plastic Deformation,	24
	Slip,	24
	Critical Resolved Shearing Stress for Slip,	26
	Twinning,	31
	Grain Boundary Sliding and Diffusional Creep,	32
	Effects of Grain Boundaries in Polycrystals,	33
	Strain Rate Effects,	33
3.5	Fracture,	34
3.6	An Introduction to Dislocation Theory,	38
	Dislocation Geometry,	38
	Dislocation Motion,	43

	Dislocation Pinning, Generation, and Interaction, 46	
3.7	An Introduction to Linear Elastic Fracture Mechanics, 50	
3.8	Use of Fracture Mechanics in Design, 62	
3.9	Elastic-Plastic Fracture Mechanics, 70	
3.10	Using the Ideas, 76	
3.11	Closure, 80	
	Questions, 80	
	References, 87	
Chapter 4	State of Stress	90
4.1	Introduction, 90	
4.2	State of Stress at a Point, 90	
4.3	Principal Normal Stresses, 95	
4.4	Principal Shearing Stresses, 100	
4.5	Using the Ideas, 105	
	Questions, 109	
	References, 111	
Chapter 5	Relationships Between Stress and Strain	112
5.1	Introduction, 112	
5.2	Concepts of Engineering Stress-Strain and True Stress-Strain, 112	
5.3	Elastic Stress-Strain Relationships, 118	
5.4	Plastic Stress-Strain Relationships, 125	
5.5	Using the Ideas, 130	
	Questions, 135	
	References, 139	
Chapter 6	Combined Stress Theories of Failure and Their Use in Design	140
6.1	Introduction, 140	
6.2	Maximum Normal Stress Theory (Rankine's Theory), 142	
6.3	Maximum Shearing Stress Theory (Tresca-Guest Theory), 144	
6.4	Maximum Normal Strain Theory (St. Venant's Theory), 146	
6.5	Total Strain Energy Theory (Beltrami Theory), 148	
6.6	Distortion Energy Theory (Huber-Von Mises-Hencky Theory), 151	

- 6.7 Failure Theory Comparison in Biaxial State of Stress, 156
- 6.8 Mohr's Failure Theory, 157
- 6.9 Summary of Failure Theory Evaluation, 162
- 6.10 Combined Stress Failure Theories as Design Tools, 163
- 6.11 Using the Ideas, 165
 - Questions, 172
 - References, 177

Chapter 7 High-Cycle Fatigue

178

- 7.1 Introduction, 178
- 7.2 Historical Remarks, 179
- 7.3 The Nature of Fatigue, 181
- 7.4 Fatigue Loading, 184
- 7.5 Laboratory Fatigue Testing, 188
- 7.6 The *S-N-P* Curves—A Basic Design Tool, 194
- 7.7 Factors That Affect *S-N-P* Curves, 198
 - Material Composition, 199
 - Grain Size and Grain Direction, 199
 - Heat Treatment, 202
 - Welding, 204
 - Geometrical Discontinuities, 207
 - Surface Conditions, 207
 - Size Effect, 213
 - Residual Surface Stresses, 213
 - Operating Temperature, 217
 - Corrosion, 220
 - Fretting, 221
 - Operating Speed, 221
 - Configuration of Stress-Time Pattern, 223
 - Nonzero Mean Stress, 226
 - Damage Accumulation, 227
- 7.8 Using the Factors in Design, 228
- 7.9 The Influence of Nonzero Mean Stress, 229
- 7.10 Using the Ideas, 236
- 7.11 Multiaxial Fatigue Stresses, 238
 - Maximum Normal Stress Multiaxial Fatigue Failure Theory, 239
 - Maximum Shearing Stress Multiaxial Fatigue Failure Theory, 240
 - Distortion Energy Multiaxial Fatigue Failure Theory, 241

- 7.12 Use of Multiaxial Fatigue Failure Theories, 244
- 7.13 Using the Ideas, 244
 - Questions, 248
 - References, 252

Chapter 8 Concepts of Cumulative Damage, Life Prediction, and Fracture Control 255

- 8.1 Introduction, 255
- 8.2 The Linear Damage Theory, 256
- 8.3 Cumulative Damage Theories, 258
 - Marco-Starkey Cumulative Damage Theory, 259
 - Henry Cumulative Damage Theory, 261
 - Gatts Cumulative Damage Theory, 263
 - Corten-Dolan Cumulative Damage Theory, 265
 - Marin Cumulative Damage Theory, 268
 - Manson Double Linear Damage Rule, 271
- 8.4 Using the Ideas, 274
- 8.5 Life Prediction Based on Local Stress-Strain and Fracture Mechanics Concepts, 281
 - Local Stress-Strain Approach to Crack Initiation, 281
 - Fracture Mechanics Approach to Crack Propagation, 293
 - Estimation of Total Fatigue Life, 304
- 8.6 Service Loading Simulation and Full-Scale Fatigue Testing, 305
- 8.7 Damage Tolerance and Fracture Control, 307
- 8.8 Using the Ideas, 312
 - Questions, 314
 - References, 328

Chapter 9 Use of Statistics in Fatigue Analysis 333

- 9.1 Introduction, 333
- 9.2 Definitions, 333
- 9.3 Population Distributions, 336
- 9.4 Sampling Distributions, 341
- 9.5 Statistical Hypotheses, 350
- 9.6 Confidence Limits, 354
- 9.7 Properties of Good Estimators, 356
- 9.8 Sample Size for Desired Confidence, 356
- 9.9 Probability Paper, 358
- 9.10 Comparison of Means and Variances, 365

- 9.11 In Summary, 371
- Questions, 371
- References, 373

Chapter 10 Fatigue Testing Procedures and Statistical Interpretations of Data 374

- 10.1 Introduction, 374
- 10.2 Standard Method, 374
- 10.3 Constant Stress Level Testing, 375
- 10.4 Response or Survival Method (Probit Method), 377
- 10.5 Step-Test Method, 379
- 10.6 Prot Method, 381
- 10.7 Staircase or Up-and-Down Method, 383
- 10.8 Extreme Value Method, 388
- 10.9 In Summary, 390
- Questions, 390
- References, 392

Chapter 11 Low-Cycle Fatigue 393

- 11.1 Introduction, 393
- 11.2 The Strain Cycling Concept, 394
- 11.3 The Strain-Life Curve and Low-Cycle Fatigue Relationships, 398
- 11.4 The Influence of Nonzero Mean Strain and Nonzero Mean Stress, 401
- 11.5 Cumulative Damage in Low-Cycle Fatigue, 404
- 11.6 Influence of Multiaxial States of Stress, 405
- 11.7 Relationship of Thermal Fatigue to Low-Cycle Fatigue, 405
- 11.8 In Summary, 407
- 11.9 Using the Ideas, 407
- Questions, 411
- References, 413

Chapter 12 Stress Concentration 414

- 12.1 Introduction, 414
- 12.2 Stress Concentration Effects, 416
- 12.3 Stress Concentration Factors for the Elastic Range, 418
- 12.4 Stress Concentration Factors and Strain Concentration Factors for the Plastic Range, 427
- 12.5 Stress Concentration Factors for Multiple Notches, 429

12.6	Fatigue Stress Concentration Factors and Notch Sensitivity Index, 430	
12.7	Fatigue Crack Growing From the Root of a Notch, 436	
12.8	Using the Ideas, 437	
	Questions, 452	
	References, 458	
Chapter 13	Creep, Stress Rupture, and Fatigue	459
13.1	Introduction, 459	
13.2	Prediction of Long-Term Creep Behavior, 461	
	Abridged Method, 462	
	Mechanical Acceleration Method, 463	
	Thermal Acceleration Method, 463	
13.3	Theories for Predicting Creep Behavior, 464	
	Larson-Miller Parameter, 464	
	Manson-Haferd Parameter, 465	
13.4	Creep Under Uniaxial State of Stress, 466	
13.5	Creep Under Multiaxial State of Stress, 471	
13.6	Cumulative Creep Concepts, 473	
13.7	Combined Creep and Fatigue, 475	
	Questions, 495	
	References, 502	
Chapter 14	Fretting, Fretting Fatigue, and Fretting Wear	504
14.1	Introduction, 504	
14.2	Variables of Importance in the Fretting Process, 505	
14.3	Fretting Fatigue, 506	
14.4	Fretting Wear, 516	
14.5	Fretting Corrosion, 519	
14.6	Minimizing or Preventing Fretting Damage, 521	
	Questions, 522	
	References, 523	
Chapter 15	Shock and Impact	526
15.1	Introduction, 526	
15.2	Energy Method of Approximating Stress and Deflection Under Impact Loading Conditions, 527	

- 15.3 Stress Wave Propagation Under Impact Loading Conditions, 533
- 15.4 Particle Velocity and Wave Propagation Velocity, 537
- 15.5 Stress Wave Behavior at Free and Fixed Ends, 542
- 15.6 Stress Wave Propagation in a Bar Under Suddenly Applied Axial Force, 544
- 15.7 Stress Wave Attenuation Due to Hysteretic Damping, 546
- 15.8 Stress Wave Propagation in a Bar Struck on the End by a Moving Mass, 550
- 15.9 Maximum Stress in a Bar Struck on the End by a Moving Mass, 557
- 15.10 Stress Wave Propagation When the Yield Point Is Exceeded, 561
- 15.11 Changes in Material Properties Under Impact Loading, 562
- 15.12 Spalling or Scabbing Under Impact Loading, 569
- 15.13 The Effects of Stress and Strain Concentrations Under Impact Loading Conditions, 572
- 15.14 Using the Ideas, 575
- 15.15 In Summary, 578
Questions, 578
References, 582

Chapter 16 Buckling and Instability

583

- 16.1 Introduction, 583
- 16.2 Buckling of a Simple Pin-Jointed Mechanism, 583
- 16.3 Buckling of a Pinned-End Column, 585
- 16.4 The Influence of End Support on Column Buckling, 589
- 16.5 Inelastic Behavior in Column Buckling, 591
- 16.6 Using the Ideas, 594
- 16.7 Lateral Buckling of Deep, Narrow Beams Subjected to Bending, 598
- 16.8 Lateral Buckling of Thin, Circular Shaft Subjected to Torsion, 602
- 16.9 Other Buckling Phenomena, 605
Questions, 605
References, 608

Chapter 17 Wear, Corrosion, and Other Important Failure Modes 609

- 17.1 Introduction, 609
- 17.2 Wear, 609
 - Adhesive Wear, 610
 - Abrasive Wear, 616
 - Corrosion Wear, 620
 - Surface Fatigue Wear, 620
 - Deformation Wear, Fretting Wear,
and Impact Wear, 621
- 17.3 Empirical Model for Zero Wear, 622
- 17.4 Using the Ideas, 627
- 17.5 Corrosion, 629
 - Direct Chemical Attack, 630
 - Galvanic Corrosion, 632
 - Crevice Corrosion, 634
 - Pitting Corrosion, 634
 - Intergranular Corrosion, 635
 - Selective Leaching, 636
 - Erosion Corrosion, 636
 - Cavitation Corrosion, 637
 - Hydrogen Damage, 637
 - Biological Corrosion, 638
- 17.6 Stress Corrosion Cracking, 638
- 17.7 Closure, 639
 - Questions, 640
 - References, 642