

**MECHANICAL
DESIGNERS'
WORKBOOK**

Distortion & Stress

Joseph E. Shigley

Charles R. Mischke

CONTENTS

Contributors ix

Preface xi

1. Sections and Shapes—Tabular Data, by Joseph E. Shigley	1
1-1 Centroids and Center of Gravity	2
1-2 Second Moments of Areas	14
1-3 Preferred Numbers and Sizes	17
1-4 Sizes and Tolerances of Steel Sheets and Bars	19
1-5 Wire and Sheet Metal	31
1-6 Structural Shapes	43
REFERENCES	43
2. Stress, by Joseph E. Shigley	45
2-1 Definitions and Notation	46
2-2 Triaxial Stress	49
2-3 Stress-Strain Relations	51
2-4 Flexure	57
2-5 Stresses Due to Temperature	64
2-6 Contact Stresses	67
REFERENCES	71
3. Deflection, by Joseph E. Shigley and Charles R. Mischke	73
3-1 Stiffness or Spring Rate	75
3-2 Deflection Due to Bending	75
3-3 Properties of Beams	77
3-4 Computer Analysis	87
3-5 Analysis of Frames	89
4. Instabilities in Beams and Columns, by Harry Herman	99
4-1 Euler's Formula	101
4-2 Effective Length	103
4-3 Generalization of the Problem	105
4-4 Modified Buckling Formulas	107

viii CONTENTS

4-5	Stress-Limiting Criterion	108
4-6	Beam-Column Analysis	113
4-7	Approximate Method	115
4-8	Instability of Beams	116
	REFERENCES	121
5.	Curved Beams and Rings, by Joseph E. Shigley	123
5-1	Bending in the Plane of Curvature	125
5-2	Castigliano's Theorem	125
5-3	Ring Segments with One Support	131
5-4	Rings with Simple Supports	133
5-5	Ring Segments with Fixed Ends	141
	REFERENCES	149
6.	Pressure Cylinders, by Sachindranarayan Bhaduri	151
6-1	Introduction	152
6-2	Design Principles of Pressure Cylinders	152
6-3	Design Loads	155
6-4	Cylindrical Shells—Stress Analysis	157
6-5	Thick Cylindrical Shells	167
6-6	Thermal Stresses in Cylindrical Shells	169
6-7	Fabrication Methods and Materials	172
6-8	Design of Pressure Cylinders	175
	REFERENCES	177
7.	Tolerances, by Charles R. Mischke	181
7-1	Tolerances	183
	REFERENCES	193
Index	194	